

CERTIFICATE OF COMPLIANCE



EL Class I

Date of issue: 24 February 2022

Valid until: 31 December 2024

EHEDG hereby declares that the product

pressure transmitter Optibar 5060 type VGK6-**-**-[LN, EZ, NB, L0, E1, E2, E3, E5, E8, AD, K0, AC, H0, L1, EK, SR, TB, U4, U6, KW, AT, TE, AR, TF, AW, AS, KY, FR]-**-**-**-**-**-**-**-**-**-**-**-**-**-**-0-**-0-b-M


from

KROHNE Pressure Solutions GmbH, Gewerbepark Meißen 14, D-32423 Minden, Germany

has/have been evaluated for compliance and meets/meet the current criteria for Hygienic Equipment Design of the EHEDG

Certificate No. EHEDG-C2200011

Signed  _____ *President EHEDG*
Hein Timmerman

Signed  _____ *EHEDG Certification Officer*
Karlijn Faber

*EHEDG
Karspeldreef 8
1101 CJ Amsterdam
Netherlands*

©EHEDG



Appendix 3

EHEDG Certification – Equipment Evaluation Form

Design Evaluation Date: 27.09.2021

EHEDG File Number: EHEDG-R2100013

Certification Type: EL CLASS I

Applicant: KROHNE Pressure Solutions GmbH

Equipment: pressure transmitter Optibar 5060 type VGK6-**-**-[LN, EZ, NB, L0, E1, E2, E3, E5, E8, AD, K0, AC, H0, L1, EK, SR, TB, U4, U6, KW, AT, TE, AR, TF, AW, AS, KY, FR]-**-**-**-**-**-**-**-**-0-b-M

Other essential identification:


Evaluated by:

Name: Dr. Jürgen Hofmann

Approved by:

Name: Andy Timperley, on behalf of the Working Group Certification

Title: AEO, Chairman of the WG Certification

Date, Signature: 17.02.2022, 

1. Results of inspection for compliance with the EHEDG Hygienic Design Criteria. Conclusion: The equipment complies with the criteria. The use of the EHEDG Certification logo is justified:	YES <input checked="" type="checkbox"/> MAYBE <input type="checkbox"/>
2. Evidence for compliance provided and convincing for Certification. Conclusion: The equipment complies with the criteria where possible. The use of the EHEDG Certification logo is justified:	YES <input type="checkbox"/>

Signature: 

Date: 10.02.2022

The original of this form will be kept by EHEDG together with the application, the inspection report, the evidence provided and any other relevant documentation, as listed on the back.

